

國立中央大學八十五學年度碩士班研究生入學試題卷

所別: 工業管理研究所 甲、乙組 科目: 統計學 共 2 頁 第 1 頁

Note: No work No points.

1. Nonconformative rate r of a truck of industrial products is to be checked. How many samples do we need for making sure the Standard Deviation of the usual estimator of r smaller than 0.01? If the rate is known to be at most 0.3, what is your answer?(20%)
2. Give three methods each to estimate the standard deviation and central location of a population from a sample.(20%)
3. F is a distribution function of $N(0,1)$. Find $F(1.64)-F(-1.96)$.(10%)
4. The load of a bridge follows a $N(20t,4)$ and the weight of cars passing the bridge follows a $N(2t,1)$. How many cars on the bridge at least would make the chance that the bridge overloads over 0.159?(t is a unit)(20%)
5. How to determine a sample size for checking a manufacturing process. (It is good enough to give idea without formula) (10%)
6. (X_1, X_2, \dots, X_n) is a normally $N(5, \sigma^2)$ distributed sample. $S_1 = \sum_1^n (X_i - 5)^2 / n$ and $S_2 = \sum_1^n (X_i - \bar{X})^2 / (n-1)$ are two estimators of σ^2 , where \bar{X} is the average of X 's. Which one is better? Why?(20%)



國立中央大學八十五學年度碩士班研究生入學試題卷

所別：工業管理研究所 甲乙組

科目：統計學

共 二 頁 第 二 頁

TABLE Values of the Standard Normal Distribution Function

z	0	1	2	3	4	5	6	7	8	9
.0	.5000	.5040	.5080	.5120	.5160	.5199	.5239	.5279	.5319	.5359
.1	.5398	.5438	.5478	.5517	.5557	.5596	.5636	.5675	.5714	.5753
.2	.5793	.5832	.5871	.5910	.5948	.5987	.6026	.6064	.6103	.6141
.3	.6179	.6217	.6255	.6293	.6331	.6368	.6406	.6443	.6480	.6517
.4	.6554	.6591	.6628	.6664	.6700	.6736	.6772	.6808	.6844	.6879
.5	.6915	.6950	.6985	.7019	.7054	.7088	.7123	.7157	.7190	.7224
.6	.7257	.7291	.7324	.7357	.7389	.7422	.7454	.7486	.7517	.7549
.7	.7580	.7611	.7642	.7673	.7703	.7734	.7764	.7794	.7823	.7852
.8	.7881	.7910	.7939	.7967	.7995	.8023	.8051	.8078	.8106	.8133
.9	.8159	.8186	.8212	.8238	.8264	.8289	.8315	.8340	.8365	.8389
1.0	.8413	.8438	.8461	.8485	.8508	.8531	.8554	.8577	.8599	.8621
1.1	.8643	.8665	.8686	.8708	.8729	.8749	.8770	.8790	.8810	.8830
1.2	.8849	.8869	.8888	.8907	.8925	.8944	.8962	.8980	.8997	.9015
1.3	.9032	.9049	.9066	.9082	.9099	.9115	.9131	.9147	.9162	.9177
1.4	.9192	.9207	.9222	.9236	.9251	.9265	.9278	.9292	.9306	.9319
1.5	.9332	.9345	.9357	.9370	.9382	.9394	.9406	.9418	.9430	.9441
1.6	.9452	.9463	.9474	.9484	.9495	.9505	.9515	.9525	.9535	.9545
1.7	.9554	.9564	.9573	.9582	.9591	.9599	.9608	.9616	.9625	.9633
1.8	.9641	.9648	.9656	.9664	.9671	.9678	.9686	.9693	.9700	.9706
1.9	.9713	.9719	.9726	.9732	.9738	.9744	.9750	.9756	.9762	.9767
2.0	.9772	.9778	.9783	.9788	.9793	.9798	.9803	.9808	.9812	.9817
2.1	.9821	.9826	.9830	.9834	.9838	.9842	.9846	.9850	.9854	.9857
2.2	.9861	.9864	.9868	.9871	.9874	.9878	.9881	.9884	.9887	.9890
2.3	.9893	.9896	.9898	.9901	.9904	.9906	.9909	.9911	.9913	.9916
2.4	.9918	.9920	.9922	.9925	.9927	.9929	.9931	.9932	.9934	.9936
2.5	.9938	.9940	.9941	.9943	.9945	.9946	.9948	.9949	.9951	.9952
2.6	.9953	.9955	.9956	.9957	.9959	.9960	.9961	.9962	.9963	.9964
2.7	.9965	.9966	.9967	.9968	.9969	.9970	.9971	.9972	.9973	.9974
2.8	.9974	.9975	.9976	.9977	.9977	.9978	.9979	.9979	.9980	.9981
2.9	.9981	.9982	.9982	.9983	.9984	.9984	.9985	.9985	.9986	.9986
3.	.9987	.9990	.9993	.9995	.9997	.9998	.9998	.9999	.9999	1.0000